

TIP147 1.5 A @ 50 V

Figure 5. Safe Operating Area

F1FRV Octobre 2010

REPLACEMENT OF DARLINGTON TIP147
BY MOSFET FOR HIGH CATHODE CURRENT




FIGURE 4. FORWARD BIAS SAFE OPERATING AREA




FIGURE 4. FORWARD BIAS SAFE OPERATING AREA